

# RINCONADA WATER TREATMENT PLANT INTERIM SITE RESTORATION PROJECT

Contract C0670, Project No. 93294057







Concrete Pipe Support Work – Before and After







Containment Berm Work – Before and After







Paving By East Clearwell – Before and After








Paving By North Floc/Sed – Before and After








Paving By West Floc/Sed – Before and After







Paving Between Ozone and Floc/Sed – Before and After







Paving South of Ozone Contactor Structure – Before and After







Paving South of Ozone Contactor Structure – Before and After

