


Coyote Creek - Large Woody Debris & Erosion William St. to Hwy 280



- Field Site Assessment
- San Jose City Parcels
- Valley Water Easement
- Valley Water Fee
- Creek




GIS themes are for illustration and general analysis purposes only and are not accurate to surveying or engineering standards. Information is not guaranteed to be accurate, current, or complete and use of this information is your responsibility.

DS Erosion Site



DS Erosion Site



DS Erosion Site



DS Erosion Site



DS Erosion Site



DS Erosion Site



DS Erosion Site



LWD 1 101925





LWD 2 1020+25





LWD 3 STA 1023+25





LWD 4 1025+00