

Coyote Creek Flood Management Measures Project

Notice of Completion of Construction

May 8, 2025

Construction Photos



Construction Photos



Before



After

Floodwall 1 – Sta 20+00 Land Side, Looking South

Construction Photos



Before



After

Floodwall 2 – Sta 28+00 (Public Storage) Land Side, Looking South

Construction Photos



Floodwall 3 – Chessington Ave/Notting Hill Dr, Looking West

Construction Photos



Floodwall 4 – Sta 10+75 Land Side of Wall (RV Storage) Looking North

Construction Photos

12/12/2023 11:31:08
37.341334° N, 121.871193° W
166 Arroyo Way
San Jose CA 95112
United States



Before



After

Floodwall 5 – Sta 19+40 Land Side of Wall, Looking South

Construction Photos



Floodwall 6 – Access Road towards Flood Gate 1, Looking North

Construction Photos



Before

2024/02/26 11:22:25



After

Floodwall 7 – Sta 10+00 Water Side of Wall, Looking South