

COYOTE WAREHOUSE PROJECT – STAGE 1

Contract C0635, Project No. 91234011

Construction Photos

Construction Photos

2



valleywater.org

Coyote Warehouse Looking East

Construction Photos

3



valleywater.org

Coyote Warehouse Looking North

Construction Photos



valleywater.org

Site Preparation and Grading for Coyote Warehouse

Construction Photos



Concrete Slab Pour for Warehouse

Construction Photos

6



valleywater.org

Installation of Building Framing, Perimeter CMU Wall and Siding

Construction Photos



valleywater.org

Cantilever Storage Racks

Construction Photos



valleywater.org

Small Parts Storage Racks

Construction Photos



valleywater.org

Grinding and Resurfacing Asphalt at Coyote Pumping Station
(Before and After)

THIS PAGE INTENTIONALLY LEFT BLANK