

## SANTA CLARA VALLEY WATER DISTRICT

### RECOMMENDATION OF CONSTRUCTION CONTRACT ACCEPTANCE

In accordance with **Article 9.10, Final Inspection and Acceptance of Work**, of the contract specifications, a final inspection was conducted on June 9, 2017 for the John D. Morgan Park Monitoring Wells Project, Contract No. C0622, Project No. 91304001. The Project Completion Letter dated September 5, 2017 indicates that the work was completed in accordance with the requirements of the contract.

It is recommended that the work under this contract be accepted by the District.

Recommended By:

#### **ORIGINAL SIGNED BY**

---

Timothy Bramer, P.E.  
Construction Manager  
Designated Engineer's Representative

---

Date

Concurrence:

#### **ORIGINAL SIGNED BY**

---

Katherine Oven, P.E.  
Deputy Operating Officer  
Water Utility Technical Support Division

---

Date

THIS PAGE INTENTIONALLY LEFT BLANK