

PERMANENTE AND HALE CREEKS CONCRETE CHANNEL REPAIR PROJECT

Contract C0707, Project No. 62084001


Construction Photos

Construction Photos




Crack Repair Work on Channel Bottom (During and Post Construction)

Construction Photos



Joint Seal Repair Work (During and Post Construction)

Construction Photos



Wall Spall Repair Work (During and Post Construction)

Construction Photos

6



valleywater.org

Steel Installation Work at Permanente Creek



Construction Photos



Steel Installation Work at Hale Creek