

SANTA CLARA VALLEY WATER DISTRICT
RECOMMENDATION OF CONSTRUCTION CONTRACT ACCEPTANCE

In accordance with **Article 9.10, Final Inspection and Acceptance of Work**, of the contract specifications, a final inspection was conducted on June 1, 2016, for the Infrastructure Reliability Portfolio 2 Water Treatment Plant Operations Building Seismic Retrofit Project, Contract No. C0596, Project No. 93764003. The Project Completion Letter dated July 14, 2016 indicates that the work was completed in accordance with the requirements of the contract.

It is recommended that the work under this contract be accepted by the District.

Recommended By:



Brandon Ponce, P.E.
Senior Civil Engineer
Designated Engineer's Representative




Date

Concurrence:



Acting for _____
Katherine Owen, P.E.
Deputy Operating Officer
Water Utility Capital Division



Date