


**SANTA CLARA VALLEY WATER DISTRICT**

**RECOMMENDATION OF THE CONSTRUCTION CONTRACT ACCEPTANCE**

In accordance with **Article 9.14, Final Inspection of Work**, of the contract specifications, a final inspection was conducted on December 31, 2017, for the El Camino Storm Drain Erosion Repair Project, Contract No. C0626, Project No. 62084001, Facility ID No. 2037. The Project Completion Letter dated March 27, 2018 indicates that the work was completed in accordance with the requirements of the contract.


It is recommended that the work under this contract be accepted by the District.

Recommended By:

  
\_\_\_\_\_  
Roger Narsim, P.E.  
Engineering Unit Manager  
Designated Engineer's Representative

3/27/18  
Date

Concurrence:

  
\_\_\_\_\_  
Ngoc Nguyen, P.E.  
Interim Deputy Operating Officer  
Watersheds Design and Construction Division

3/27/18  
Date

**THIS PAGE INTENTIONALLY LEFT BLANK**