



Valley Water

Clean Water • Healthy Environment • Flood Protection

Canoas Creek Rodent Damage Repair Project

Completion of Construction Contract
Project No. 30114002, Contract No. C0612

Presentation Topics

- Project Objective
- Project Description
- Project Location
- Project Construction Costs
- Construction Photos

Project Objective

The objective of the Canoas Creek Rodent Damage Repair Project is to:

- Reduce the risk of levee and embankment slope failure due to damage caused from burrowing animals and
- Reduce frequent maintenance costs associated with routine bank erosion repair.



Project Description

The Canoas Creek Rodent Damage Repair Project included:

- Reconstruction of approximately one mile of creek channel embankment and levee between Nightingale Drive and Hillsdale Avenue and
- Installation of erosion control fabric over the surface of the reconstructed creek bank.

Canoas Creek between Nightingale Drive and Hillsdale Avenue, San Jose



Project Construction Costs

Construction:

- \$5,448,300.00 – Contract Award Amount
- \$5,437,253.15 – Final Contract Amount (0.20% Decrease)

Funding Sources:

- Watershed Stream Stewardship Fund

Construction Photos

8



valleywater.org

Construction Photos

9



valleywater.org

Construction Photos

10



valleywater.org

Construction Photos

11



valleywater.org

THIS PAGE INTENTIONALLY LEFT BLANK