

CROSS VALLEY AND CALERO PIPELINES INSPECTION AND REHABILITATION PROJECT

Contract C0650, Project No. 95084002

Construction Photos

Construction Photos



Appurtenance Vault Work – Before and After

Construction Photos

3



valleywater.org

Replacement of Air Release Valves

Construction Photos



4



Cochrane Valve Vault Construction

Construction Photos

5



valleywater.org

Removal of Valves at Peet Road and Calero Modulating Vault

Construction Photos

6



valleywater.org

Valve Replacement at Peet Road Vault

Construction Photos

7



valleywater.org

Internal Carbon Fiber Reinforcement Repair of PCCP

THIS PAGE INTENTIONALLY LEFT BLANK